

Fabrication


- Secondary mirror has been diamond turned by II-VI Inc.
 - Copper Substrate (5:1 aspect ratio)
 - Gold coating






Metrology for a φ-polynomial

Proposed acceptance testing/characterization configuration for the secondary mirror



Surface Form Error



RMS = 0.328λ

